

Переходной Тройник 90°


Tees 90°

Tés à 90°

Tes 90°



01 10 1004 000



d	G	D	D1	I	I1	Z	Gr	Кол.
20	"1/2	30	30	28	28	12	39	B 70
25	"1/2	37	30	33	28	15	57	B 50
25	"3/4	37	37	33	33	15	65	B 40
32	1 "	45	45	38	38	17	100	B 30
40	1" 1/4	53	53	45	45	23	145	B 20
50	1" 1/2	64	64	50	50	28	226	B 12
63	1" 1/2	77	65	72	65	34	375	B 6
63	2 "	77	76	72	70	34	330	B 9
75	1" 1/2	92	65	84	75	40	564	B 3
75	2" 1/2	88.5	88.5	82	82	38	473	B 3
90	1" 1/2	110	65	99	84	48	865	C 8
90	3 "	105	105	97	97	46	770	C 10
110	1" 1/2	132	65	119	86	58	1432	C 5
110	2 "	132	76	119	86	58	1440	C 5
110	2" 1/2	132	92	119	102	58	1480	C 5
110	3 "	132	110	119	109	58	1603	C 4
110	4 "	132	132	119	119	58	1640	C 4

Арт. №
01 10 1004 004
01 10 1004 005
01 10 1004 006
01 10 1004 007
01 10 1004 008
01 10 1004 009
01 10 1004 010
01 10 1004 011
01 10 1004 012
01 10 1004 030
01 10 1004 013
01 10 1004 040
01 10 1004 014
01 10 1004 015
01 10 1004 016
01 10 1004 017
01 10 1004 018