

Переходной Тройник 90° НР/В


Tees 90° F/M

Tés à 90° F/M

Tes 90° H/M



01 10 1310 000



d	G	D	I	Z	I ₁	Z ₁	Gr	Кол.
20	"1/2	26	28	11	31	16	23	B 100
20	"3/4	26	28	11	35	19	25	B 90
25	"1/2	33	33	14	36	21	43	B 60
25	"3/4	33	33	14	38.5	22.5	45	B 50
25	1"	33	33	14	41.5	22.5	46	B 50
32	"3/4	64	64	50	50	28	60	B 30
32	1"	77	65	72	65	34	61	B 30

Арт. №

01 10 1310 004

01 10 1310 005

01 10 1310 008

01 10 1310 009

01 10 1310 010

01 10 1310 014

01 10 1310 015